



Go: Air-Assisted Airless Curriculum

Paint Course: Introduction to Air-Assisted Airless

Lesson Name	Part	Score	Cues	Difficulty
Warm Up	Panel Vertical	--	Yes	Normal
Flat Surfaces	Panel Vertical	70	Yes	Normal
Horizontal Flat Surfaces	Panel Horizontal	70	Yes	Normal
Curved Surfaces 1	Panel Curve	70	Yes	Normal
Curved Surfaces 2	Panel Curve Complex	70	Yes	Normal
Curved Surfaces 3	Sphere Half	70	Yes	Normal
Small Round Surfaces 1	Cylinder Horizontal	70	Yes	Normal
Small Round Surfaces 2	Cylinder Vertical	70	Yes	Normal
Small Round Surfaces 3	Cylinder Combined	70	Yes	Normal
Large Round Surfaces	Cylinder Large	70	Yes	Normal
Outside Corners	Box	70	Yes	Normal
Interior Corners 1	Corner	70	Yes	Normal
Interior Corners 2	Corners Interior	70	Yes	Normal
Open Work	Panel with Cutouts	70	Yes	Normal
Grooves	Panel with Grooves	70	Yes	Normal
Complex Shapes	Panel with Shapes	70	Yes	Normal
Curved Surfaces Test	Panel Curve Complex	70	No	Normal
Small Round Surfaces Test	Pipes Combined	70	No	Normal
Interior Corners Test	Corners Interior	70	No	Normal
Complex Shapes Test	Panel with Shapes	70	No	Normal